

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
14	IS&R	L28	59	(("1411442") or ("2711491") or ("3021442") or ("3271601") or ("1716689") or ("2295143") or ("2474495") or ("2590187") or ("2914070") or ("3276646") or ("4119249") or ("4210230") or ("4424841") or ("4515300") or ("3482125") or ("3707037") or ("4849665") or ("4028568") or ("4033531") or ("4260125") or ("4426593") or ("4835428") or ("4922151") or ("4980589") or ("2778053") or ("5629575") or ("5760513") or ("3983429") or ("4039872") or ("5696415") or ("6124567") or ("4360749") or	USPA T	2004/09/3 0 12:35	
15	BRS	L29	68757 5	generator alternator	USPA T; DERW ENT	2004/09/3 0 12:53	
16	BRS	L30	23112	29 and (mount\$4 bracket)	DERW ENT	2004/09/3 0 12:53	
17	BRS	L31	4067	30 and (automotive automobil\$2 vehicle)	DERW ENT	2004/09/3 0 12:53	
18	BRS	L32	2163	31 and (engine motor)	DERW ENT	2004/09/3 0 12:42	
19	BRS	L33	434	32 and side	DERW ENT	2004/09/3 0 12:54	
20	BRS	L34	101	33 and (hole opening groove)	DERW ENT	2004/09/3 0 12:54	
21	BRS	L35	101	34 not 12	DERW ENT	2004/09/3 0 12:44	
22	BRS	L36	11752 7	generator alternator	JPO	2004/09/3 0 13:01	
23	BRS	L37	6480	36 and (mount\$4 bracket)	JPO	2004/09/3 0 13:01	

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
24	BRS	L38	934	37 and (automotive automobil\$2 vehicle)	JPO	2004/09/30 13:01	
25	BRS	L39	281	38 and side	JPO	2004/09/30 13:02	
26	BRS	L40	71	39 and (hole opening groove)	JPO	2004/09/30 13:02	
27	BRS	L41	33326	generator alternator	EPO	2004/09/30 13:01	
28	BRS	L42	2646	41 and (mount\$4 bracket)	EPO	2004/09/30 13:01	
29	BRS	L43	534	42 and (automotive automobil\$2 vehicle)	EPO	2004/09/30 13:01	
30	BRS	L44	80	43 and side	EPO	2004/09/30 13:02	
31	BRS	L45	14	44 and (hole opening groove)	EPO	2004/09/30 13:02	